

# Examining the Role of Wheel/Rail Interaction in a Derailment

1



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# TSB Mission

To advance transportation safety in the air, marine, rail and pipeline modes of transportation that are under federal jurisdiction  
It is not the function of the Board to assign fault or determine civil or criminal liability.



# TSB Mission accomplished by

- conducting independent investigations
- identifying safety deficiencies
- identifying causes and contributing factors
- making recommendations
- publishing reports





# Wheel/Rail Derailments

High lateral-force rail rollover, wheel climb or wheel drop in due to a combination of train speed, under-elevated curve, lowered L/V threshold due to 2-point contact or wheel profile, uneven or degraded rail fastener resistance to dynamic wide gauge



# Grey, Alberta

Derailment of 28 hopper cars loaded with frac sand and two DP locomotives at Mile 96.4 Grande Cache Subdivision on 29 October 2016



HEAVY HAUL SEMINAR • MAY 2-3, 2018


Transportation Safety Board  
of Canada




Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# Grey, Alberta





HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada




Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# The Train

- DP train pulled by five GE ET44AC locomotives, 3 on the head-end and 2 positioned at the end of the train
- 102 loaded covered hopper cars, 14,586 tons and 4,652 feet long





**Train A45851 length and tonnage profile**





**GE ET44AC Locomotive**



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**



# Emergency

- The train was descending a 1% grade through a 6° RH curve at 27 mph
- DB was in position DB5 on the lead locomotive
- DB was disabled on the 3<sup>rd</sup> head end locomotive
- Train brakes were not applied





HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada


**WRI 2018**

# Point of Derailment

- The first car behind the head end locomotives remained upright and did not derail
- The 2<sup>nd</sup> to the 29<sup>th</sup> car derailed



Leading wheel sets of trailing trucks of 2<sup>nd</sup> and 3<sup>rd</sup> locomotives (No. 4 axles in direction of travel) derailed. R3 wheels were derailed to the outside of the high rail and the L3 wheels were derailed to the inside of the low rail.



# Derailment Investigation

- track maintenance practices
- curve superelevation
- rail wear and two point contact
- train handling, use of dynamic brake on DP powered heavy unit trains on mountain grades



# Derailment Investigation

- Train dynamics analysis of in-train and transformed lateral forces
- Lateral-to-vertical (L/V) ratios



# The Track

- Class 2 track posted maximum speed 25 mph
- 11.6 MGT in 2016
- Mix of HW and SW ties, 4 spikes/14" DS plate
- Fully anchored, crushed rock ballast





# The Track

- 1991 Algoma 115lb CWR high rail, 2016 Evraz 115 lb CWR low rail
- Flange lubricators located at Mile 96.2 and 100.1



# High Rail



115lb 1991 Algoma CWR  
7mm head wear  
8 mm flange wear



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# Plug Rail

- 34' plug rail installed in high rail at POD months previously
- Both joints fully bolted at time of installation
- Both joints recovered intact





HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**



## South plug rail joint

115lb 1991 Algoma Rail. Note missing bolts and wheel flange contact on top of gauge joint bar



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# Low Rail Replacement

- tie installation in June 2016 and the low rail changed out in September 2016
- low rail securement strengthened due to increased spiking and gluing of the spike holes
- With new, full-height rail, the average superelevation on the curve was reduced by 0.42 inch to 0.99 inch



# POD Curve

- The length of curve was 1762 feet.
- The curve extended from Mile 96.24 to Mile 96.57.
- The average degree of curvature was about 6 degrees (i.e., ranging from  $5.94^{\circ}$  to  $6.06^{\circ}$  ).






# POD Curve

- The superelevation ranged from 0.51 inches and 1.28 inches.
- The average superelevation was 0.99 inches.
- The design speed was 26.7 mph.
- The balanced superelevation was 2  $\frac{3}{4}$  inches.





# Hopper Cars

42' Frac Sand Covered Hopper

59' Covered Grain Hopper



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# Short Covered Hopper Cars

For cars of the same weight, in some circumstances, shorter cars can exert higher forces on the rail in curves (i.e., unbalanced centrifugal  $L/V$  and/or transformed lateral forces when the cars are in jackknifed position under buff in-train forces) than longer cars



# Short Covered Hopper Cars

The shorter distance between sets of trucks in short cars will bring the pressure bulbs produced by each set of trucks closer together and create a larger area of overlapping pressures and lateral forces



# Length of car/truck center distance ratio

Car Number	Outside Length	Truck Center	Ratio	Load Limit	Volume
CP 601324	59	46	1.28	205,900	4550
CN 110092	59	46	1.28	222,800	4550
ALPX 628141	59	46'-3"	1.28	204,800	4550
<b>CEFX 312560</b>	<b>42</b>	<b>28'-8"</b>	<b>1.46</b>	<b>232,800</b>	<b>3260</b>
ALNX 396053	59	46	1.28	200,000	4550
CN 109410	59	46	1.28	224,100	4550
CN 109231	59	46	1.28	223,600	4550



# Transformed Lateral Force

$$L_{tr} = L_{bar} * L_c / L_{tc}$$






# Wheel/Rail Interface Forces

The lateral and vertical forces at the wheel/rail interface are a result of interaction between:

- track geometry
- vehicle dynamics
- wheel/rail profile



# Wheel/Rail Interface Forces



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada





Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# Worn vs New Rail Contact



# Two Point Contact



# Train Operations Simulator (TOS) and Quasi-static Lateral Train Stability (QLTS) Models



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# QLTS Simulation Results

- The locomotive/locomotive lateral force calculated was 12,066 pounds and 0.19 truckside L/V ratio.
- The lateral force for the locomotive/car combination was 12,247 pounds with 0.19 truckside L/V ratio



# QLTS Simulation Results

- The lateral force for the car/car combination was 8,224 pounds with 0.18 truckside L/V ratio



# TOS Simulation Results

- The maximum longitudinal in-train drawbar forces on the locomotives were below 100 kips when the locomotive derailed at 27 mph.
- These values were considered moderate and non-causative for well-supported and maintained track.





# Train Energy and Dynamics Simulation (TEDS)

- in-train buff force between 85 kips and 115 kips (2 locos at DB5)
- Total lateral forces and L/V ratio = dynamic curving + unbalanced centrifugal + transformed lateral force



# TEDS Results

- Total truckside L/V ratios were about 0.51 for the sand cars and 0.48 for the locomotives
- Lateral force at the leading outside wheel was approximately 22 kips for the sand cars and 26 kips for the locomotives.



# Derailment Mechanism

- high rail in the 6° right-hand curve rolled over as the head end of the train travelled over the plug rail
- Underelevated curve resulted in higher lateral forces exerted on high rail



# Derailment Mechanism

- 2-point contact at the wheel-rail interface likely occurred, resulting in a lower L/V derailment threshold
- dynamic brake resulted in a further increase in lateral forces on the high rail by the head-end locomotives



# Increased Potential for High Rail Rollover

- Uneven fastener resistance between the high and low rail
- reduced superelevation after the low rail was replaced with a new full-height rail





## Elastic Fasteners on high rail, spikes on low

TSB investigation reports R04T0161 and R11T0162, and TSB Railway Occurrence R06T0125



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**



# Rail Fastener Systems

## Elastic Fastener



## Spikes



HEAVY HAUL SEMINAR • MAY 2-3, 2018

Transportation Safety Board  
of Canada



Bureau de la sécurité des transports  
du Canada

**WRI 2018**

# Rail

- With the high rail close to its wear limits, wheel/rail contact was closer to the field side of the high rail, resulting in a lower lateral-to-vertical derailment threshold
- High rail likely rolled or canted out sufficiently to allow low rail wheels to drop in





# Cause

High rail rolled over due to a combination of dynamic brake and train speed on the under-elevated curve, lowered L/V threshold due to 2-point contact on the worn high rail, and uneven high/low rail fastener resistance to dynamic gauge widening





**South plug rail joint bar**



# Safety Action Taken

- Gauge restrain measuring
- Review of superelevation standard
- Mandatory use of air in combination with DB
- Increased Engine Service Office presence
- Increased track patrol frequency



# QUESTIONS?

- Derailment reports available at:
- <http://www.tsb.gc.ca/eng/rapports-reports/rail/index.asp>

