

# Characterizing the Effects of Rail Surface Conditions on Noise and Track Components

**Shankar Rajaram, PhD**

**Noise and Vibration Program Manager**

**Sound Transit**



RAIL TRANSIT SEMINAR • APRIL 30, 2018



**WRI 2018**

# Acknowledgements

1. **ST Engineering – Han Xiangdong, Jason Bailey, Kerry Pihlstrom, Ben Neeley, Chad Brown, Peter Brown, Senior Mgmt & other staff**
2. **ST Operations – George McGinn, Udaysinh Parmar, Pete Magadia, Steve Bose, Mike Larson, KCM field inspectors & Senior Mgmt.**
3. **ST Construction Management & SQA**
4. **ST Consultants – Tony Bohara, James T. Nelson & Hugh Saurenman**
5. **ST Construction Partner – Stacy Witbeck Inc. (& Progress Rail)**
6. **ST CMC Partner – HatchMott McDonald**
7. **ST Design Partner – HNTB**




# Overview of this Presentation

1. Introduction to Failing Track Component – Rail Clips
2. Root Cause Investigation Strategy
3. Onboard Noise and Track Vibration Results
4. Rail Surface Condition and Corroborative Tests
5. Plausible Root Cause & Remedy Discussion



# What are E-Clips?

High Resilient DF Fastener





Rail Clip



E-Clip



# E-clip Failure Mode




Location 1: Front Arch (lazy bend)


U-Link Clip Failure Location: Center Leg

Location 2: Rear Arch (tight bend)


Fatigue Failure




# E-clip Failure Problem



# ST Investigation Overview




# Onboard Noise Data – ATS






# Measure e-clip Acceleration on Site (Wilson Ihrig Test)



# Measure e-clip Acceleration in Lab (Wilson Ihrig Test)

10



RAIL TRANSIT SEMINAR • APRIL 30, 2018

SOUNDTRANSIT

WRI 2018

# Key Learnings

Track System Natural Resonance: ~800-900 Hz

The clips are subject to strains that exceed their design limit


Use of a bigger clip with higher elasticity and strain capacity can potentially arrest the failure rate




# Use of PR Clips to Arrest Failure Rate



- The PR clip is more robust with higher strain limit
- Clip resonance shifted to ~950 Hz



# Trial Section with PR Clips



- About 1000 feet replaced with PR Clips
- No PR Clip failure in 9 months



# Hypothesis to Identify Root Cause

Track System Natural Resonance: ~800-900 Hz

E-Clip Natural Resonances: ~800-900 Hz


What is unique about the e-clip failure areas?

Perhaps external driver at 800 – 900 Hz resulting in  
Coincidence Phenomenon?



# What is the Potential Source Driving the Resonance?

15




Wheel?

LRV truck?

Rail?



# Recent Rail Grinding Signature of Transit Properties in North America




- Rail roughness wavelength peak at 30 mm
- The peaks are caused by:

*Rail grinder speed— 4 mph*  
*Grinding motor— 3600 rpm*





# Rail Surface – Visual Inspection



Grinding Marks Pitch

1.2 in

&

1.1 in



# Rail Roughness Measurements – ATS

## E - CLIPS FAILURE MAP



SOUTH BOUND TRACK				NORTH BOUND TRACK				
WEST RAIL		EAST RAIL		WEST RAIL		EAST RAIL		
FIELD SIDE	GAGE SIDE	GAGE SIDE	FIELD SIDE	FIELD SIDE	GAGE SIDE	GAGE SIDE	FIELD SIDE	
								1210+00
								1169+00
								1168+00
X								
X X								
X								1167+00
	X		X					
X	X							
X	X	X						1166+00
X								
			X					1165+00
	X							1164+00
	X							
X X X X	X		X					1163+00
X				X				
X				X				



# Rail Roughness Results

SB West Rail = 15 dB

E - CLIPS FAILURE MAP



29.8 mm = 890 Hz  
(at 55 mph train speed)



# What is the Potential Root Cause Fix?

20


**FOCUS ON THE RAIL GRINDING FINISH !**



RAIL TRANSIT SEMINAR • APRIL 30, 2018

 **SOUNDTRANSIT** **WRI 2018**

# Transit Rail Grinding – Status Quo




**EN 13231-3:2012**  
Limit Proposed by Rail Grinding Companies

**ISO 2095: 2005**  
ST's Current Rail Grinding Limit



# Sound Transit's Revised Rail Roughness Limits



Rail Grinding Limit

Rail Polishing Limit




# Revised Rail Grinding Strategy

1. Separate metal removal step (rail grinding) from rail polishing step
2. Use different roughness limit for the two steps and monitor during intermediate rail grinding stages



# How to Meet New Grinding Spec?



- Employ different grinding speeds and grit sizes for the two steps
- Factor the track time and budget needed to grind the rails





# Why 50mm Roughness Wavelength?

Rail Roughness Wavelength	25 mm	32 mm	40 mm	50 mm (Safe for N&V)	63 mm	80 mm
Train Speed						
30 mph	536 Hz	426 Hz	335 Hz	<b>268 Hz</b>	213 Hz	168 Hz
35 mph	626 Hz	497 Hz	391 Hz	<b>313 Hz</b>	248 Hz	196 Hz
40 mph	715 Hz	568 Hz	447 Hz	<b>358 Hz</b>	284 Hz	224 Hz
45 mph	805 Hz	639 Hz	503 Hz	<b>402 Hz</b>	319 Hz	251 Hz
55 mph	983 Hz	780 Hz	615 Hz	<b>492 Hz</b>	390 Hz	307 Hz



# Revised ST Rail Grinding Requirements

## Step 1 – Grinding

Step 1a – Check rail roughness to verify compliance

## Step 2 – Polishing (higher grinding speed and finer grit stones)

Step 2a – Check rail roughness to verify compliance to polishing limit

## Step 3 – Confirm conformance to rail roughness limit before leaving



# Summary

- E-clip failure investigation unexpectedly showed rail surface condition as the plausible compounding root cause.
- Bigger rail clips are currently tried as a mitigation option to reduce the propensity for failures at extreme conditions.
- Grinding the rails to tighter tolerances would lead to smoother finish and can potentially eliminate the root cause for failure.
- Sound Transit has revised the rail grinding specification.

