

# Derailment Prevention – From Causes to Cures

*Brad Kerchof*  
*Director Research & Tests*



# Derailment Prevention – From Causes to Cures



1. Switch point wheel climb
2. Rail roll-over
  - Adverse rail profiles
  - Adverse wheel profiles



## Switch Point Wheel Climb



Track supervisor to mechanical supervisor: “The last 100 cars made it over this switch point, then that car derailed. And you’re blaming the point???”





## What three conditions are present in most switch point wheel-climb derailments?

1. A gapped, worn or broken switch point




## What three conditions are present in most switch point wheel-climb derailments?



1. A gapped, worn or broken switch point
2. A worn wheel profile – one with a small flange root radius and (often) a sharp edge on the tip of the flange

Can a wheel be condemned for a vertical flange?

Yes – but only if the wheel gauge contacts the flange 1" above the tread. Very few wheel flanges achieve 90°.



## Why does a worn wheel increase risk of wheel climb?



A worn flange root allows the flange tip to get much closer to the point




## What three conditions are present in most switch point wheel-climb derailments?

1. A gapped, worn or broken switch point
2. A worn wheel profile
3. Tracking position – the worn wheel is shifted toward the switch point





## A wheel climbs a switch point



Worn profile and a sharp edge on the flange tip



The worn flange is tracking close to the stock rail, approaching a gapped point




The flange climbs the switch point





## What is a good indicator that a switch point problem is developing?



Wheel flange contact at the front of the point



## One more switch point wheel climb



Main track, no. 10 spring switch to a siding, LH diverging point



No indication of wheel climb on the point

However, there was a cross-over wheel mark on the RH point back at the heel block





# One more switch point wheel climb



- ✓ Slightly worn point
- ✓ Evidence of flange contact at the tip (tracking position)
- ✓ Worn (but not condemnable) wheel flange



## Switch point wheel climb - the cure


Maintain your switch points with worn wheel flanges in mind!

- Worn flanges are more likely to pick a poor-fitting point
- Worn flanges are common
- Most wheels that climb points are not condemnable
- Good-fitting points should be able to accommodate worn flanges






## Rail Roll-over: Adverse (High) Rail Profiles



## What affects rail stability?



Rail stability (roll potential) affected by:

- magnitude & location of V
- magnitude & location of L

Location of V affected by:

- rail profile
- wheel profile



## How do we describe a high rail profile?

Two profile measurements:


- B/H (base / height)
- Head slope (2 points ½" either side of rail center)

What makes an adverse profile?


- One that produces field-side wheel contact

On NS, our thresholds for concern are

- B/H < 0.35 (new 136RE, B/H = 0.42)
- Head slope > 5°



## Adverse high rail profiles



Profiles from 5 rail roll-over derailments

What do you notice?

- Significant side wear
- Significant head slope
- Likely some field-side wheel contact






## How does an adverse profile develop?




Worst case: Prolonged train operation and many grinding cycles over outward-canted rail




New ties or gaging (with adzing) will change orientation of a previously canted rail; rail will be “set up” to 0° cant



# How does an adverse profile cause trouble?



Brown trace - 3° canted rail  
Red trace – worn wheel




Brown trace - 0° canted rail  
Red trace - worn wheel


Contact has changed to two-point, and tread contact has moved toward field side!




## How does an adverse profile cause trouble?



# VAMPIRE wheel/rail contact plots




Slightly worn wheel on 3° canted rail




Slightly worn wheel on 0° canted rail - tread moves toward field side (2-point contact)

3.5 mm tread-hollow wheel on 0° canted rail (extreme 2-point contact)





# VAMPIRE - predicted L/V



File 1: v1141.lis

Inputs: rail & wheel profiles,  
track geometry, equipment  
features & conditions

Output: truckside L/V

When L/V exceeds B/H  
(could be either rail), there  
is a risk of rail roll.




# Adverse rail profile - the cures

## Strengthen track


- Elastic fasteners instead of spikes

## Reduce forces

- Manage rail profiles by grinding



## Grinding as the cure



Graph: High rail before and after grinding; 1/8" was removed from the field corner.

Photo: Same rail after grinding (3° cant). Wheel contact has been moved to a much more desirable location.



# Adverse rail profile - the cures

## Strengthen track

- Elastic fasteners instead of spikes

## Reduce forces

- Manage rail profiles by grinding
- TOR friction control

## Inspection

- Look for evidence of spike lift










## Rail Roll-over: Adverse Wheel Profiles

When do wheel profiles become the problem?

1. Does the wheel exceed the 4 mm tread-hollow standard? (not common)
2. Evidence of unusual wheel contact leading to the POD?
3. What do wayside detectors tell us?
4. What does VAMPIRE modeling reveal?



## Hollow-tread wheels



### AAR standard

- 5 mm off a rip track
- 4 mm on a rip track



## Unusual wheel / rail contact near the POD



These 3 unusual conditions were noted on the low rail leading up to the POD:


1. Scuff marks on field side of the head
2. Wheel flange contact on the gage face
3. Evidence that rail has been canting out under load



# Wayside detector data

## Truck Gauge Spread Force (TSGF) History

● B-Truck    ◆ C-Truck    ▲ D-Truck    ■ A-Truck






# VAMPIRE wheel contact plots

In all tracking positions – from high rail flanging to low rail flanging, the L3 wheel always contacts the field edge of the high rail.

Consequences of this type of contact:

- ▶ high gage-spreading forces
- ▶ poor rail stability






## VAMPIRE L/V modeling – wheel or rail?

Which has a greater impact on L/V?

- worn wheels on new rail (red/green) or
- new wheels on worn rail (blue/yellow)?

In this case, worn wheels produced higher L/V.

This, plus the other evidence, allowed us to identify hollow-tread wheels as the primary cause.



# Adverse wheel profile: the cure

## Long term

- The industry is evaluating whether there is justification for reducing the current hollow-tread limits (5 mm off rip track, 4 mm on rip track)

(My hope - 3 mm)

## Short term

- Pay close attention to rail profiles
- Corrective grinding
- Look for evidence of spike lift



# Thank you!

