


Controlling Rail Cant and Lateral Forces By Managing the Wheel/Rail Interface



Brad Kerchof
May 9, 2013


Description of rail cant

Cant is the amount of rail rotation referenced from standard tie plate position (typically 1:40 inward)



Outline

- Review results from the Wills test site (2011)
- Describe work done at the Hardy test site (2012 – 2013)
 1. Track conditions
 2. Video
 3. Graph of lateral forces



Wills rail cant test site, 2011

Established April, 2011

- Wills, WV
- 7.8° curve, 4" elevation, 25 mph
- Strain gages for L & V forces



Track Conditions

- Cut spikes , 8x18" plates
- Gage > 57-1/4"
- Cant 2°high rail, 3°low rail



Wills – track conditions

Track conditions on June 6



- High rail – Victor plates with Pandrol fasteners (strong restraint)
- Low rail – worn 8x18” tie plates with cut spikes (weak restraint)
- Gage – 56-3/8”
- Abundant gage face lube
- No top of rail FM



Wills - video of low rail



Wills 2011 - lateral forces



Wills - track conditions

Track conditions after June 21



- Low rail - Victor plates with Pandrols
- Gage opened to 56-3/4"



Wills - video of low rail with Victor plates



Wills 2011 - lateral forces



2012 - 2013 Research Objective

What caused the dramatic force reduction at Wills?

- Gage?
- Elastic fasteners?
- Rail orientation?



Hardy rail cant test site

Established March, 2012

- Hardy, VA
- 5.7° curve, 3-1/2" elevation, 35 mph
- Strain gages for L & V forces

Track Conditions

- Cut spikes , 8x18" plates
- Gage 57"
- Cant 2° high rail, 3° low rail
- Gage face lube
- No TOR FM



Low rail cant – Wills vs. Hardy



At Wills, 3° of cant was spike lift and evidence of rail rotation.



At Hardy, 3° of cant was difficult to explain.





Hardy - condition of plates on low rail



Point of maximum wear on field side $> 1/8$ " (yellow arrow); the shape of the worn rail seat changes the pivot point (red arrow).



Impact of worn plates on cant




Hardy - video of worn plate on low rail




Hardy 2012 – lateral forces at start of test

Loaded 286k Trains, Lead Wheels vs. Lateral Force (kips)



Loaded 286k Trains, Trail Wheels vs. Lateral Force (kips)




Hardy 2012 – TOR as test variable




Hardy 2012 - lateral forces with TOR On / Off

Loaded 286k Trains, Lead Wheels vs. Lateral Force (kips)



Loaded 286k Trains, Trail Wheels vs. Lateral Force (kips)



2012 - 2013 Research Objective

What caused the dramatic force reduction at Wills?

- Gage?
- Elastic fasteners?
- Rail orientation?

Test plan:

- Replace the worn plates on low rail with new 8x18" plates
- Keep rail profile, gage & friction constant



Hardy - low side plate renewal



Hardy – rail / tie plate contact



Old plate from tangent – rail base is contacting most of rail seat



Old plate from body of curve – rail base is contacting only field side of rail seat



Hardy – rail / tie plate contact



Hardy - comparison of new & worn plates



New plate 1-1/8"



Worn plate < 1"




Hardy - video of new plate under low rail




Hardy 2012 - lateral forces with new plates

Loaded 286k Trains, Lead Wheels vs. Lateral Forces (kips)



Loaded 286k Trains, Trail Wheels vs. Lateral Forces (kips)




Results with Victor plates



Results with TORFM




Loaded 286k Trains, Lead Wheels vs. Lateral Force (kips)



Results with 8 x 18 plates, cut spikes



Loaded 286k Trains, Lead Wheels vs. Lateral Forces (kips)



2012 - 2013 Research Objective


What caused the dramatic force reduction at Wills?

- Gage?
- Elastic fasteners?
- Rail orientation?



Conclusions from work at Hardy & Wills

1. Rail orientation is important: lateral forces are greater on canted rail
2. Worn tie plates can be a hidden cause of improper rail orientation, and can be a significant contributor to rail cant defects



Conclusions from work at Hardy & Wills

3. By controlling gage, rail profile, rail orientation and friction, it is possible to reduce lateral forces significantly.


At both Wills and Hardy, we were able to reduce lateral forces from 10 - 15 kips to 5 – 10 kips by managing the wheel/rail interface.



Questions or Comments?



How low can we go?



Wills test site, Fall, 2012

- TOR unit installed at beginning of test curve
- Lead wheel average forces dropped to 3 – 9 kips, the lowest forces measured in the test

