



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



Detail Fracture Defects The Canadian TSB Experience

George Fowler, P.Eng. , Track & Infrastructure Engineer,
Don Mustard, B.Sc. , Senior Accident Investigator

Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada

Transportation Safety Board of Canada

Presentation at the 2013 Wheel Rail Interaction Conference

Heavy Haul Seminar

May 8 – 9, 2013



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Outline for Today's Presentation

- About the TSB
- TSB vs NTSB
- Detail Fracture Wheel/Rail Investigations
- TSB Watchlist





Board Objectives

- To advance transportation safety by:
 - Conduct independent investigations and, if necessary, public inquiries
 - Make findings as to causes and contributing factors
 - Identify safety deficiencies
 - Make recommendations
 - Report publicly.





Unique Features of TSB's Enabling Legislation

- The TSB is independent from any other federal department or organization
- The TSB reports directly to Parliament
- The Board does not assign fault or determine civil or criminal liability





Unique Features of TSB's Enabling Legislation

- The Board shall not refrain from reporting fully because fault or liability may be inferred from findings.
- The Board's findings are not binding on parties to any legal, disciplinary or other proceedings





TSB vs NTSB

- The Chair and Board Members have no role in the fact finding portion of the investigation
- The TSB is not required to determine probable cause (although we sometimes do!)





TSB vs NTSB

- Limited use of observers.
- The IIC is the spokesperson of the investigation
- The TSB is the keeper of rail occurrence data





The TSB Rail & Pipeline Investigation Branch

- RPIB – approximately 25 staff
- 13 Regional Investigators in 8 offices
- 5 Head Office Investigators – specialists, standards and technical coordinators
- 1 pipeline investigator
- 3 regions – East, Central, West





TSB Watchlist

- As with the NTSB, the Board maintains a list of safety issues that pose the greatest risk to Canadians. In Rail, these include:
- On-board video and voice recorders
- Following signal indications
- Passenger trains colliding with vehicles.





Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada

Detail Fracture Defects

The Canadian Experience



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Main Track Derailments due to Fatigue Defects





Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013





Detail Fracture Defects

- A type of transverse defect
- Cannot be detected visually
- Usually only identified prior to failure by ultrasonic testing
- Unpredictable growth rate – may appear and fail between tests





Detail Fracture Defects

- Caused by rolling contact fatigue
- High traffic densities and loading
- Initiate at inclusion, surface cracks or internal longitudinal separation (shell)
- Can occur in any rail, but more likely to develop in older rails lacking mechanical properties, strength and quality of newer rails






Advancing Transportation Safety

- Recommendations on fatigue, shell or head checking (eg NTSB 2006 New Brighton) very broad – difficult or impossible to implement
- The Department of Transport (TC) establish minimum standards for the quality and strength of maintenance rails. (R07-01)
- The Department of Transport establish standards requiring that rails approaching their fatigue limit be replaced. (R07-02)






- 20 loaded coal cars derailed while travelling across reversing 8° curves over the bridge
- 12 cars fell off the bridge, spilling about 1400 tons of coal into the river
- Extensive damage to the track and bridge





Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada




HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada




HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada




HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013

Recovered Rail Pieces and Fastenings

- Point of derailment was a broken rail on a tie plate
- Located 67 feet west of the east abutment (about 1 car length) on the north (high) rail and in the entry spiral of an 8-degree (about 218 m radius) left-hand curve



Direction of travel



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



- Fractures A and B matched
- More battering on fracture B
- Crack initiated from a shell at the lower gauge corner.
- Lip created by plastic metal flow caused by wheel/rail contact overstress.





Crack
origin at a
shell in
the lower
gauge
corner

Beach marks in the fatigue crack region





- Fine head checking, minor spalling, no visible evidence of shelling or corrugation.
- Rail showed 12 mm head wear and 6 mm flange wear.
- Rail did not exceed the specified limits for wear loss.



Fracture Face A



Beach marks in the fatigue crack region



Fracture Face B



- Fractures A and B matched
- More battering on fracture B
- Crack initiated from a shell at the lower gauge corner.
- Lip created by plastic metal flow caused by wheel/rail contact overstress.



Rail Material

- Rail was 141-pound continuous welded head-hardened rail rolled in Oct 2001 and installed in July 2002
- The rail material met railroad specification requirements
- Brinell hardness (363 HB head surface, 352 HB head core)
 - Ultimate tensile strength was 1258 MPa (min 1172 MPa required)
 - Elongation was within the 6 to 12% range typical for rail materials





Rail Testing

- Laboratory analysis concluded defects were present for some time
- Previous UT showed an indication near the location on the bridge where the rail broke
- Indication was attributed to a thermite weld upset/finish
- Action taken:
 - Testing frequency was further increased
 - Indications interpreted as weld must be confirmed visually
 - All suspect indications are hand-tested





Conclusion

- The train derailed when a pre-existing detail fracture defect grew to a critical size leading to the rail breaking under the train.
- The detail fracture defect grew from a shell at the lower gauge corner at a lip created by plastic metal flow caused by wheel/rail contact overstress.
- Neither the train operation, the condition of the rolling stock, fastenings nor the bridge timber under the rail break were considered contributory to the accident.





Conclusion

- The detail fracture defects grew quickly, consistent with heavy loading
- Shells and other defects can mask detail fractures (the UT signal reflects off the shell)
- Contributing factors to derailments:
 - Difficulty of detecting these types of defects using UT
 - Rapid unpredictable growth rate of the defects
 - Ineffective rail lubrication program





Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013




Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013







Conclusion

- Transverse defect in 190' plug of 1976 115lb relay rail
- initiated at a sub-surface crack and propagated downwards in the head
- Surface shelling and cracking prevented proper identification of internal rail defects on ultrasonic test done nine days prior to derailment
- Indications not checked by hand testing
- Grinding done on maintenance rail 14 months earlier before it was laid on the bridge





So what has been learned?

- Understanding wheel/rail interaction is essential
- Effect of wear and rolling contact fatigue on development of defects
- Rail maintenance strategies to reduce the stress state
- Rail performance and defect management





Rail Maintenance

- Grinding:
 - Remove surface damage such as corrugations, head checking, shells due to fatigue under rolling contact conditions
 - Restore correct head profile, contact geometry and relieve contact stress
- Lubrication:
 - Wayside flange and top-of-rail lubricator system
 - Monitoring of lubrication effectiveness visually and by measurement of coefficient of friction at the wheel/rail interface






Ultrasonic NDT Rail Testing


- Primary risk-control method used to detect internal rail defects and manage fatigue
- Reliable, cost-effective, efficient and productive way to test rails in track
- Rail head contact system that relies on a smooth rail surface
- Operator training, experience, expertise and interpretation skills



Ultrasonic NDT Rail Testing

- Transport Canada requires ultrasonic testing for internal defects based on class of track
- Annually for Class 4 thru 6, in tracks where the annual tonnage is 25 mgt or more and in Class 3 track over which passenger trains operate
- Railways typically exceed this requirement







Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013



Phased Array Ultrasound

- Ultrasound and integrated rail profiling
- Laser profiling system resolves rail shape, and ultrasonic beams “steered” to correct for rail wear adjusting probes to target the proper reflection surface on any cross-section
- Beam sweeping can confirm defect information automatically from the truck without stopping for a hand test – higher inspection speeds
- Non-contact means not dependent on clean rail surface for testing integrity



Canada



HEAVY HAUL SEMINAR • MAY 8 - 9, 2013

WRI 2013