


# Measuring Rail Cracks Using Eddy Current

Brad Kerchof  
Eric Eberius  
May 8, 2013



# RCF cracks on high and low rails



# Rail cracks develop into spalls



# Cracks, spalls and plastic flow and spalls



# Cracks can develop into transverse defects



2012 data: a third of NS's defects and service failures are TDs, and a high percentage of these originate at the running surface



# Low rail before grinding



# Low rail after pass 1



## Low rail after pass 2



## Low rail after pass 3



# Low rail after pass 4



## Low rail after pass 5

Even after 5 passes, cracks are still visible!

Should we have made additional grinding passes to remove the cracks?



# Why do we grind?

1. Remove RCF defects, including spalls, corrugations and fatigued metal
2. Maintain a clean surface for ultra-sonic testing
3. Restore a rail profile that improves axle steering



High rail pre-grind (gage side right)



High rail post-grind



# Why do we grind?



Low rail pre-grind (gage side left)



Low rail post-grind

Should we have made additional grinding passes to remove the spalls and cracks?




# Deutsche Bahn Crack Growth Model

Crack growth divides into three stages



## Head Checks – Path of crack and speed of crack growth



St = damaging depth  
 VT = visual check  
 ET = eddy-current test  
 UT = ultrasonic check



# Can we measure crack depth?

- Knowing crack depth can improve the effectiveness of grinding program.
- The Rohmann “Draisine”
- Walk-behind
- Measures one rail at a time



# Draisine measurement head



Four eddy current probes:

- probes 1 and 2 cover the head
- probes 3 and 4 cover the gage corner
- each probe covers a 7 mm “active area”



# Phase 1– Measurement pre- and post-grind

- Will the Draisine measure a change in crack dimension?
- Will grinding stone marks interfere with the eddy current signal?



# Draisine pre-grind crack measurements

- Low rail
- Horizontal scale: 100 m per graph
- Vertical scale: 0 – 5 mm; different mm are color-coded, and each bar represents the worst cracks found in 1 m
- Cracks were measured between 1 and 3 mm on ground track, and over 5 mm on the two bridges



# Draisine post-grind crack measurements


- After 5 grinding passes, results show a significant reduction in crack size (especially over the 2 bridges)
- Grinding marks do not appear to be a problem



# Draisine measurements during grinding

We collected crack data over a 35-meter long section of low rail after each grinding pass. Results shown are pre-grind and post-grind after 2<sup>nd</sup>, 3<sup>rd</sup> and 5<sup>th</sup> passes.

- Crack size decreased with grinding, and this decrease was captured by the Draisine.



# Phase 2 – Describe the measurements

- Determine what the Draisine is measuring – is it crack length, depth, or some combination?
- Quantify crack depth – that is what is needed for rail maintenance!




# Crack verification, rail sample no.107


1. Collect crack measurement data (high rail of 2° curve)
2. Identify three one-foot samples that have RCF cracks rail)
3. Cut out the samples and perform a cross-section analysis



# Crack verification, rail sample no.115



Flashbutt weld separating Steelton & Nippon rails






Steelton 1989 rail on left, Nippon 1990 rail on right




## Cross-sections from two of the samples





# Rail sample sections nos. 36, 107 and 115






# Section 36 = 2.1mm damage depth (Draisine)



# Section 36 = 2.1mm damage depth (Draisine)





# Section 36 = 2.1mm damage depth (Draisine) At 21° = 1.8mm damage depth (actual)






# Section 107 = 2.1mm damage depth (Draisine) At 18° = 1.7mm damage depth (actual)




Draisine on-site EloRail Scan evaluation software results





# Section 115 Steelton = 1.9mm damage depth (Draisine) At 25° = 2.0mm damage depth (actual)




# Section 115 Nippon = 0.4mm damage depth (Draisine) At 28° = 0.3mm damage depth (actual)




Cracks are not discernible on rail head



# Steelton to Nippon raw data



# Steelton to Nippon processed data



# Crack orientation - high vs. low rails



# Getting the most out of this technology

- What is the crack growth rate?
- Is it worth removing cracks?
- Will crack removal extend rail life?



# Questions?

