

Effect of Top of Rail Friction Control on Rail Performance

Richard Reiff AAR/TTCI

Kevin Conn Norfolk Southern Railroad



Presentation Overview

- Project background and objectives.
- Site description.
- Monitoring efforts.
- Significant results.
- Issues and concerns.
- Questions/Discussion.

Acknowledgments



Tim Drake	(MoW-Engineering)
Chris Carney	(MoW-Engineering)
Shane Rice	(MoW-Engineering)
Jack Stepp Jr.	(MoW-Engineering)
Ricky Lee	(MoW-Engineering)
Bruce Gibson	(MoW-Engineering)
Tim Rahe	(MoW-Engineering)
Bob Blank	(R&T)
Brad Kerchof	(R&T)
Hayden Newell	(R&T)
Jack Hughes	(R&T)
Tim Caldwell	(R&T)
Kaiya Boykins	(R&T)
Jim Harris	(R&T)
Danny Sanderson	(R&T)
Brent Ballew	(R&T)
John Wachsmuth	(R&T)
Scott Keegan	(R&T)
Owen Vogt	(R&T)
Ray Griffith	(C&S-Engineering)
Allen Hammitt	(C&S-Engineering)
Don Dawson	(C&S-Engineering)
Don Wilhem	(C&S-Engineering)




Rick Kilpatrick
Tom Solano
Bea Raul
Semih Kalay
Gilbert Lucero
Dan Szablewski
Rachel Anaya




Kevin Adkins
Bill Fazio
Bob Letterle
Ward Powell
Glen Appleby
Petar Gueorguiev
John Cotter

Wheel/Rail Interface Management

Extending Rail/Wheel Life



Implementing Top of Rail Friction Control Benefits, Implementation Issues



Project Overview and Justification

- Previous AAR and member railroad demonstrations of TOR
 - Carefully controlled implementation, maintenance, inspection.
 - Limited curvatures (e.g. UP site only 10° curves).
 - Insufficient controls – traffic, rail age, rail types.
 - Results encouraging.
 - Suggest rail wear savings > 40%.
- Need for “real world” results.
 - Everyday conditions of maintenance and inspection.
 - Range of curvatures.


Previous AAR Demonstrations on NS

- Locomotive-based TOR
 - Captina Secondary (Powhatan Point, OH)
 - Equipment logistics issues.
- Wayside-based TOR
 - Captina Secondary (Powhatan Point, OH)
 - Concentrated on curving force performance.
 - Insufficient time/traffic density for rail wear study.
 - Eastern Megasite (Bluefield, WV)
 - Demonstrated reduced curving forces.
 - Rail wear comparison compromised by traffic density (i.e. location), rail metallurgy and age.


New Opportunity - Old Joe to White

- 20 miles of new rail (dual) installed in July 2009.
- Desire to build test on controls similar to long term demonstrations, such as UP Tehachapi site.
- To do this (i.e. compare TOR rail performance to non-TOR rail performance) requires:
 - Same rail metallurgy, age and train traffic.
 - Limit variables of location (use same line segment).
 - Range of curvatures.
 - Loaded coal trains (HAL) with mixed freight.

Test Site Characteristics




Test Site Characteristics




- 3°-12° curves, simple and compound, level grade.

Test Zones – GF/TOR & GF Only



- West zone (~9 miles) had GF and TOR.
- East zone (~9 miles) had GF only.
- 2 mile ‘transition’ zone.

GF and TOR Equipment Locations



GF and TOR Equipment



Gage Face
(2) 55" bars/rail, 48 ports/bar.



Top of Rail
(1) 55" bar/rail, 3 ports/bar.

Train Traffic (Heartland Corridor)

- Primarily loaded coal.
 - 286,000 lb. cars.
 - Head-end power.
 - 35 mph track speed.
- Also subjected to
 - Empty coal.
 - Mixed freight, grain, double stacks.
 - Bi-directional mine pick-ups and setoffs.
 - Variable train speeds.



NS Old Joe Monitoring Efforts

- Rail Wear
 - MiniProf[®] used to take rail profiles.
 - 18 curves (9 GF/TOR zone, 9 GF only zone).
 - 12 measurements total per curve in full body, six on the high rail and six on the low rail.
 - Measurements made before and after grinding (~4 months).
- Rail Surface Performance
 - Dye penetrant inspections, 3 locations/curve.
- Equipment performance (RPM), maintenance, repair history.
- Rail grinding history.
- Accumulated tonnage determined for each curve.

Measuring Railwear - MiniProf®




Determined Metrics

$$\text{Wear Rate} = \frac{\text{Metal Wear}^1}{\text{Traffic Density}^2}$$


Railhead Surface Cracking (Qualitative)

¹ vertical height, area


² million-gross-tons (MGT)




Rail Wear Test Curves




Curve Characteristics - Curvature



Curve Characteristics - Elevation




Curve Characteristics - Length



GF Zone


GF/TOR Zone

Curve Characteristics - Direction




GF Zone
 GF/TOR Zone


Monitoring GF & TOR Performance



GF & TOR Equipment Status




MGT – Crossovers & Branch Lines



Location of Test Curves & Crossovers

- Area between Old Joe and White is double-tracked.
- All test curves are located on track 1.
- Between Old Joe and White, trains can change from track 1 to 2 or vice versa multiple times.



Approach 1 - Train Tracking & MGT



Vertical Force Cribs (2)


AEI Reader

Wheel Sensor

Approach 1 - Train Tracking & MGT



Approach 1 - Train Tracking & MGT



Approach 2 - Train Tracking & MGT



- Route history for every train tracked from Dispatcher's display.

Approach 2 - Train Tracking & MGT

Train Route History

White			Delorme				Beech Creek			
M2 White Switch	M2 White - Thacker	M2 Thacker - Delorme	M2 Delorme Xover	M2 Delorme - Vulcan	M2 Vulcan - Cedar	M2 Cedar - Beech Creek	M2 Beech Creek Xover			
MID Trk White Switch			M12 Delorme Xover				M12 Beech Creek Xover			
M1 White Switch	M1 White - Thacker	M1 Thacker - Delorme	M1 Delorme Xover	M1 Delorme - Arrow	M1 Arrow Switch	M1 Arrow - Vulcan	M1 Vulcan - Cedar	M1 Cedar - Beech Creek	M1 Beech Creek Xover	M1 Beech Creek -

+

Train Tonnage Reports

= Accumulated MGT per curve

Rail Wear Test Curves and ID Codes



Limited groupings used for this presentation

Curvature range	TOR + GF	GF Only
3°	R, T	A, E
5°-6°	M, N, O, S, U, V	B, C, F, G, H
12°	P	J



Typical Time/MGT Wear Plot Curve V

Data collected at Pre- and Post-Grinding







Profile Changes after 70 MGT

GF/TOR left



12 ° curves

GF only right



Rail Performance - Wear

Curves $\sim 3^\circ$ After 60 MGT, 18 months



- Mixed reduction in GF/TOR vs. GF only zones.
- Low rail shows slightly higher vertical wear rate in GF/TOR zone.
- Wear rate values still very low

Rail Performance - Surface Fatigue/Cracking



Curves $\sim 3^\circ$ After ~ 60 MGT, 12 months



- Left view – typical high rail with GF lubrication and TOR applied (curve R).
- Right view – typical high rail GF lubrication only (curve E).

Rail Performance - Wear

Curves $\sim 5^\circ - 6^\circ$ After 60 MGT, 18 months



- Vertical wear rate, area loss show lower rates from GF/TOR compared to GF only.

Rail Performance - Surface Fatigue/Cracking



Curves ~ 5° - 6° After 60 MGT, 18 months



- Left view – typical high rail with GF lubrication and TOR applied (Curve O).
- Right view – typical low rail GF lubrication only (Curve C).

Rail Performance - Wear

Curves $\sim 12^\circ$ After ~ 60 MGT, 18 months



- No benefit on low rail vertical wear rate, area loss shows both rails benefit from GF/TOR compared to GF only.

Rail Performance - Surface Fatigue/Cracking

Curves ~ 12° After 60 MGT, 12 months



- Left view – typical high rail with GF lubrication and TOR applied (Curve P).
- Right view – typical low rail GF only (Curve J) .


Vertical wear and Area Loss show significant benefits from TOR

- Less metal removed during grinding operations in GF+TOR zones compared to GF
- Potential benefits
 - Less metal removed during programmed grinding
 - Extended time between grinding periods




Reduced Rail Grinding in TOR Zone

Vertical wear/grinding at center of rail (not rate)




Reduced Rail Grinding in TOR Zone

Head area removed (not rate)



Some things did not go as planned

- Why did RCF performance on Curves S and T show more cracking than other curves in TOR territory?
- Location at major branch line junction.
- Frequent
 - Train braking.
 - Backup moves.
 - Trains off branch with no TOR.
- Potential solution
 - Install TOR on branch leg.



Implementation Issues

Day to Day Real World Events

- Maintenance of applicators
 - Repairs, adjustments
 - Filling
 - Additional inspections – how to tell if it is working?
- Logistics during major trackwork (tie, surfacing, etc)
 - Remove, reinstall applicator bars
- Vandalism
 - Does everyone in the county now have a 12 volt battery?



Deployment Experiences for Wayside TOR

- Manpower to maintain systems is key.
 - TOR spacing > GF spacing which increases manpower requirements.
- Must understand movement of ALL train traffic in area.
- Minimize number of systems to reduce manpower and material cost while still achieving benefits.
- Remote Performance Monitoring needs to be rethought in 'remote' areas so that real time reporting can be achieved.
- Training of personnel for 'buy-in' to potential benefits.
- Need a 'quantitative' way to access surface cracking (i.e. depth) and integrate into grinding rail for profile.
- Robust way to determine tonnage in an area (e.g. tie plate).

Summary: Implementing an Improved Rail Friction Control Program

- Results suggest significant savings can be achieved
 - Less grinding per cycle OR extend time between grinding.
 - Rail wear starting to show lower rates in TOR zones.
 - Needs consistent, reliable application.
- Improve Gauge Face lubrication first
 - Acquire improved applicators, premium grease/lubricant .
 - Ensure spacing, operation provides uniform lubricant
- Site audit to determine location for TOR applicators.
 - Mix with existing GF units.
 - Avoid too close together.
- Personnel training
 - Need buy in.
 - Education on differences between TOR and GF.
 - Products, applicators and inspection
- Monitoring equipment
 - Not yet user friendly and low cost.
- Enforcement
 - Management buy in

Thank you